Oil Field Environmental Incident Summary

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: DELORES USA 1

Field Name: FLAXTON Well File #: 9739

Date Incident: 5/20/2015 Time Incident: 13:00 Facility ID Number:

County: BURKE Twp: 163 Rna: 91 Sec: 11 Qtr: SE SE

Location Description:

Submitted By: Gary Watson Received By:

Contact Person: Mark Bonnie

103 1st Avenue, NE Mohall, ND 58761

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:1.5 MileDistance Nearest Water Well:1.5 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	3	Barrels	3	Barrels	3	barrels	
Brine	2	Barrels	2	Barrels	2	barrels	ı

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 7/12/2015 Clean Up Concluded: 5/25/2015

Risk Evaluation:

No explosion or health hazard risk.

Areal Extent:

15' x 20'

Potential Environmental Impacts:

Affected area is 15' x 20' - shallow pipeline rupture - soil impact only.

Action Taken or Planned:

Steve Boutilier - NDIC Field was notified regarding the event. The surface owner, Mrs. Able and the tenant farmer, LaVern Peterson have been notified regarding the event. Petro Harvester plans to immediately excavate and haul-off the affected soil to an approved disposal facility. The flowline from the well to the battery will be repaired and pressure tested. The excavated soil will be replace with black dirt suitable for cultivation.

Wastes Disposal Location: Approved waste disposal facility.

Agencies Involved:

	_
	pdates
.,	nnatae
v	Duales

Date: 5/20/2015 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 8/10/2015 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12:07 8/10/2015.

No sign of spill at the time of inspection.

Request sampling from the responsible party.